



## 1. Chassis


















2 Shaft has to fit tightly




www.3drcmodels.com 1 - 11












www.3drcmodels.com 2 - 11












13





i

You can choose motor RPM. For faster driving use 500 -1000 RPM. I have used 1000 RPM.













www.3drcmodels.com 4 - 11










21

## 2. Interior







www.3drcmodels.com 6 - 11










www.3drcmodels.com 7 - 11

## 3. Body











www.3drcmodels.com 8 - 11












www.3drcmodels.com 9 - 11











www.3drcmodels.com 10 - 11



www.3drcmodels.com 8 - 11